



Example Facility Agency SemiAnnual

Report run at: 2/9/2024

StartDate: 7/1/2023 EndDate: 12/31/2023 Is HON: No Regulation: TX 28VHP

Comp Types: Connector, Pump, Valve, PRV

Unit Type: Location Unit

Include DORs in Leak %: Yes

Units: ALKY

Location Unit: ALKY

Regulation: TX 28VHP

Comp. Type	Description	Months					
		July	August	September	October	November	December
Valve	Beginning Count	1453	1453	1453	1453	1453	1453
	Added / Reactivated Count	0	0	0	0	0	0
	DeActivated Count	0	0	0	0	0	0
	Total Count	1453	1453	1453	1453	1453	1453
	TUx Count	10	10	10	10	10	10
	DTM Count	102	102	102	102	102	102
	NDE Count	1	1	1	1	1	1
	UTM Count	0	0	0	0	0	0
	All Others	1350	1350	1350	1350	1350	1350
	DTM Inspections	0	0	0	2	0	0
	NDE Inspections	0	0	0	0	0	0
	UTM Inspections	0	0	0	0	0	0
	All Other Inspections	0	7	1332	0	0	1332
	Total Inspections	0	7	1332	2	0	1332
	Total DOR	0	0	0	0	0	0
	Leaks	0	0	0	0	0	0
	Leak %	0	0	0	0	0	0
Missed First Attempts	0	0	0	0	0	0	
Missed Final Repair	0	0	0	0	0	0	
Comp. Type	Description	July	August	September	October	November	December
Pump	Beginning Count	15	15	15	15	15	15
	Added / Reactivated Count	0	0	0	0	0	0
	DeActivated Count	0	0	0	0	0	0
	Total Count	15	15	15	15	15	15
	TUx Count	0	0	0	0	0	0
	Total Inspections	8	9	8	8	8	15
	Leaks	0	0	0	0	0	0
	Leak %	0	0	0	0	0	0
	Missed First Attempts	0	0	0	0	0	0
	Missed Final Repair	0	0	0	0	0	0
Comp. Type	Description	July	August	September	October	November	December
PRV	Beginning Count	2	2	2	2	3	3
	Added / Reactivated Count	0	0	0	1	0	0
	DeActivated Count	0	0	0	0	0	0
	Total Count	2	2	2	3	3	3
	TUx Count	0	0	0	0	0	0
	Total	0	2	0	0	3	0
	Leaks	0	0	0	0	0	0
	Leak %	0	0	0	0	0	0
	Missed First Attempts	0	0	0	0	0	0
	Missed Final Repair	0	0	0	0	0	0
Comp. Type	Description	July	August	September	October	November	December
Connector	Beginning Count	4821	4821	4821	4821	4821	4821
	Added / Reactivated Count	0	0	0	0	0	0
	DeActivated Count	0	0	0	0	0	0
	Total Count	4821	4821	4821	4821	4821	4821
	TUx Count	0	0	0	0	0	0
	Total	521	920	895	482	1158	785
	Leaks	0	0	0	0	0	0
	Leak %	0	0	0	0	0	0
	Missed First Attempts	0	0	0	0	0	0
	Missed Final Repair	0	0	0	0	0	0
Overall Leak %		0.00%	0.00%	0.00%	0.00%	0.00%	0.00%