



OGI Full Data Leak History

StartDate: 7/1/2021

EndDate: 11/30/2022

Unit Type: Location Unit

Regulations: All Regulations

Units: LUnit 1, LUnit 3, LUnit 5, LUnit 6, LUnit 7

Comp Types: All Component Types

UNIT: LUnit 3 **SIZE:** **LOCATION:** Circulation Pumps with Associated Piping **PROFILE:** Active **DOR STATUS:**

TAG: OGI Spot 02 **AREA:** **STREAM:** OGI Stream **TUWHY:** **DOR AUTH BY:**

TYPE: OGI Spot, , **SUBAREA:** **ISOLATABLE:** No **NEXT ACT:** **EST REP DATE:**

PHYS STATE: GV **CVS:** No **DTM HOW:**

M21 Leaks

LeakDate	Leak Def	Regs	LkPpm	Bkgd	EmPt		1stAtt Done	1stReT Done	FinalRes Done	CloseDate	CloseWhy
10/19/22	500	EPP	5000	0	Bonnet						
						DateDue	12/18/22	12/18/22	12/18/22		
						Status	18 days	18 days	18 days		

Att Date	AttType	AttMethod	AttBy	AttComment	InspDate	Insp Why	Tech	PPM	Analyzer	AVO Result	AVOType	InspComment
					10/19/2022	2ndReTry	Devin Moody	5000	phx21-0001			

UNIT: LUnit 5	SIZE:	LOCATION: Service Tank Meter	PROFILE: Active	DOR STATUS:
TAG: OGI Spot 03	AREA:	STREAM: OGI Stream	TUWHY:	DOR AUTH BY:
TYPE: OGI Spot, ,	SUBAREA:	ISOLATABLE: No	NEXT ACT:	EST REP DATE:
PHYS STATE: GV		CVS: No	DTM HOW:	

AVO Leaks

LeakDate	AVOType							1stAtt Done	1stVerify Done	FinalRes Done	CloseDate	CloseWhy
07/01/21	OGI							DateDue	07/31/21	07/31/21	07/31/21	
								RespS	07/01/21	07/02/21	PastDue	
Att Date	AttType	AttMethod	AttBy	AttComment	InspDate	Insp Why	Tech	PPM	Analyzer	AVO Result	AVOType	InspComment
					7/1/2021	Annual	Austin Regan			Fail		
7/1/2021	Simple	Clean	Austin Regan								Simple	
					7/2/2021	Optical Gas Image	Austin Regan			Fail		
					7/3/2021	Optical Gas Image	Austin Regan			Pass		
					7/4/2021	Optical Gas Image	Austin Regan			Fail		

Target Image



Inspection Image 7/1/2021



UNIT: LUnit 6	SIZE:	LOCATION: Barrel T3000 #0053	PROFILE: Active	DOR STATUS:
TAG: OGI Spot 03A	AREA:	STREAM: OGI Stream	TUWHY:	DOR AUTH BY:
TYPE: EHatch, ,	SUBAREA:	ISOLATABLE: No	NEXT ACT: ReTest	EST REP DATE:
PHYS STATE: GV		CVS: No	DTM HOW:	

AVO Leaks												
LeakDate	AVOType							1stAtt Done	1stVerify Done	FinalRes Done	CloseDate	CloseWhy
04/05/21	OGI				DateDue	05/05/21	05/05/21	05/05/21				
					RespS	PastDue	04/20/21	PastDue				
Att Date	AttType	AttMethod	AttBy	AttComment	InspDate	Insp Why	Tech	PPM	Analyzer	AVO Result	AVOType	InspComment
					4/5/2021	Optical Gas Image	Devin Moody			Fail		
					4/20/2021	AVO ReTest	Thomas Wilson			Fail		

Target Image



UNIT: LUnit 7	SIZE:	LOCATION: PVV ON TOP OF WATER TANK #0065	PROFILE: Active	DOR STATUS:
TAG: OGI Spot 04A	AREA:	STREAM: OGI Stream	TUWHY:	DOR AUTH BY:
TYPE: PVV, ,	SUBAREA:	ISOLATABLE: No	NEXT ACT: ReTest	EST REP DATE:
PHYS STATE: GV		CVS: No	DTM HOW:	


AVO Leaks

LeakDate	AVOType							1stAtt Done	1stVerify Done	FinalRes Done	CloseDate	CloseWhy
04/06/21	OGI							DateDue 05/06/21	05/06/21	05/06/21		
								RespS PastDue	04/23/21	PastDue		
Att Date	AttType	AttMethod	AttBy	AttComment	InspDate	Insp Why	Tech	PPM	Analyzer	AVO Result	AVOType	InspComment
					4/6/2021	Optical Gas Image	Devin Moody			Fail		
					4/23/2021	AVO ReTest	Thomas Wilson			Fail		

Target Image



Inspection Image 4/6/2021



UNIT: LUnit 7	SIZE:	LOCATION: E Hatch Water Tank 1 #00067	PROFILE: Active	DOR STATUS:
TAG: OGI Spot 05B	AREA:	STREAM: OGI Stream	TUWHY:	DOR AUTH BY:
TYPE: EHatch, ,	SUBAREA:	ISOLATABLE: No	NEXT ACT: ReTest	EST REP DATE:
PHYS STATE: GV		CVS: No	DTM HOW:	

AVO Leaks

LeakDate	AVOType							1stAtt Done	1stVerify Done	FinalRes Done	CloseDate	CloseWhy
04/06/21	OGI							DateDue 05/06/21	05/06/21	05/06/21		
								RespS PastDue	04/23/21	PastDue		
Att Date	AttType	AttMethod	AttBy	AttComment	InspDate	Insp Why	Tech	PPM	Analyzer	AVO Result	AVOType	InspComment
					4/6/2021	Optical Gas Image	Devin Moody			Fail		
					4/23/2021	AVO ReTest	Thomas Wilson			Fail		

Target Image

18/04/2018 13:51:10 Lat: 3

