

# Simplified Maintenance Report

Report run at: 2/7/2023

Unit Type: Location Unit

Comp Types: All Component Types

Units: Compressor Station

Unit	Tag	Leak Def	LkDate	Last Ppm	Type	Sub T	Sub Sub	Phy St	Sz	Location	Area	DTM How	EmPt	NextAct	1stAtt By	1stRet By	FinalRes By
Compressor Station	fnt ldr cyl 4 discharge cylinder- S side Compressor 6300	AVO	10/21/21		Compressor			GV		front loader on cylinder 4 discharge cylinder C6300 SW Side					11/20/21	11/20/21	11/20/21
<b>1. Record the Attempt Date.</b> <b>2. Who did the Attempt?</b> <b>3. Select the Attempt Type (Check one box.)</b> <b>4. Select Attempt Method from attached list.</b>															<b>DirMaint?</b>		
															5.) Y / N		
Compressor Station	fnt ldr non cyl 3 discharge cyli C6500 tag 0356	AVO	10/21/21		Compressor			GV		front loader on cylinder 3 discharge cylinder C6500 - N Side					11/20/21	11/20/21	11/20/21
<b>1. Record the Attempt Date.</b> <b>2. Who did the Attempt?</b> <b>3. Select the Attempt Type (Check one box.)</b> <b>4. Select Attempt Method from attached list.</b>															<b>DirMaint?</b>		
															5.) Y / N		
Compressor Station	Leak - 2" PRV horn N of Fuel Gas Scrbr - OGI Spot 9	AVO	07/18/19		PRV	Atmos		GV		2" PRV horn N of Fuel Gas Scrubber					08/17/19	08/17/19	08/17/19
<b>1. Record the Attempt Date.</b> <b>2. Who did the Attempt?</b> <b>3. Select the Attempt Type (Check one box.)</b> <b>4. Select Attempt Method from attached list.</b>															<b>DirMaint?</b>		
															5.) Y / N		
Compressor Station	Leak - 2" sc W side of BV 1ft SE of Fuel Filter E side of N comp skid - OGI Spot 24	AVO	10/14/19		Connector	Threaded		GV		2" screw connection W side of ball valve 1ft SE of Fuel Filter E side of North compressor skid					11/13/19	11/13/19	11/13/19
<b>1. Record the Attempt Date.</b> <b>2. Who did the Attempt?</b> <b>3. Select the Attempt Type (Check one box.)</b> <b>4. Select Attempt Method from attached list.</b>															<b>DirMaint?</b>		
															5.) Y / N		